## **Inspection Report**

provided by:



#### **Sunshine Inspections Inc.**

Inspector: Jimmie Fuller 3707 Fairway Road Sebring Fl. 33872 863-382-6111 Licensed Contractor J&N Homes Inc. RR282811529 www.sunshineinspections.net

## Property Address:



#### **Client Information**

**Client Name** 

**Client Phone** 

#### **Property Information**

Approximate Year Built1964Approximate Square Footage2604Number of Bedrooms - Bath3/2

#### **Inspection Information**

**Inspection Date** 

**Inspection Price** 

Realtor

### Disclaimer

#### WITHIN THE SCOPE OF THE INSPECTION

• The scope of this inspection and report is limited to a visual inspection of the systems and components as listed below, in order to identify those, if any, which may need replacement or repair. See ASHI® Standards of Practice for a detailed description of the scope of inspection. (www.ashi.org.)

#### **Exterior:**

Landscaping, Retaining Walls, Gutters, Downspouts, Sidewalks and Driveways (both the condition of and as they affect foundation drainage,) Roof, Chimney, Flashing, and Valleys, (for evidence of water penetration and a description of materials,) Siding, Fascia, Soffit, Walls, Widows, Doors, Foundation, Attached Porches/ Decks/ Balconies/ Patios/ Garages (both structural and condition of.)

#### Interior:

Plumbing System: Water Supply/Drains/Vents/Water Heaters/Fixtures, and Locating (But Not Testing) Shut Off Valves; Electrical System: Service Drop, Service Panel, Ground Wire, GFCI Plugs, Switches, Receptacles, Installed Fixtures, and Smoke Detectors; Heating/Cooling System: Permanent Systems, Operating Controls/Filters/Ducts, Insulation, Vapor Barrier, and Ventilation; Bathrooms/Kitchen/Other Rooms: Doors/Windows/Walls/Floors (as to general condition), Cabinets, Counter tops, and Installed Fixtures; Structure: Ceilings/Walls/Floors, Stairs/Basements/Attic/Crawl Spaces (if readily accessible)(as to evidence of water damage and general condition.)

- The scope of the inspection is limited to the description and the general condition of the above systems.

#### **OUTSIDE THE SCOPE OF THE INSPECTION**

• Any area which is not exposed to view or is inaccessible because of soil, walls, floors, carpets, ceilings, furnishings, lack of access or crawl spaces or any major system (water or electrical systems, heating system, or air conditioner) that is not currently functional is not included in this inspection.

The inspection does not include any destructive testing or dismantling. Client agrees to assume all the risk for all conditions which are concealed from view at the time of the inspection. This is not a home warranty, guarantee, insurance policy, or substitute for real estate disclosures which may be required by law. Whether or not they are concealed, the following are outside the scope of the inspection;
Building code or zoning ordinance violations - Thermostatic or time clock controls or Low Voltage wiring systems - Geological stability or soils conditions - Water softener or water purifier systems or solar heating systems - Structural stability or engineering analysis - Saunas, steam baths, or fixtures and equipment - Building value appraisal or cost estimates - Pools or spa bodies or sprinkler systems and underground piping - Radio-controlled devices, automatic gates, elevators, lifts, and dumbwaiters - Furnace heat exchanger, freestanding appliances, security alarms or personal property - Specific components noted as being excluded on the individual system inspection form - Adequacy or efficiency of any system or component - Prediction of life expectancy of any item.

- The Inspector is a home inspection generalist and is not acting as an engineer or expert in any craft or trade. If the Inspector recommends consulting other specialized experts, Clients do so at Client's expense.

#### **CONFIDENTIAL REPORT**

• The written report to be prepared by the Inspector shall be considered the final and exclusive findings of the Inspector/Inspection Company regarding the home inspection at the Inspection Address. The inspection report to be prepared for the Client is solely and exclusively for the Client's own information and may not be relied upon by any other person. Client agrees to maintain the confidentiality of the inspection report and agrees not to disclose any part of it to any other person with the exception of the seller and/or the real estate agents directly involved in this transaction. Client(s) or the inspector may distribute copies of the inspection report to the seller and real estate agents directly involved in this transaction, but neither the seller nor the real estate agent are intended beneficiaries of this Agreement or the inspection report. Client agrees to indemnify, defend, and hold the Inspector/inspection Company harmless from any third party claims arising out of the Client's or Inspectors distribution of the inspection report.

#### **DISPUTES**

• Client understands and agrees that the Inspector/Inspection Company is not an insurer, that the price paid for the subject inspection and report is based solely on the service provided. Client also agrees that any claim of failure in the accuracy of the report shall be reported to the Inspector/Inspection Company within five business days of discovery and that failure to notify the inspector within that time period shall constitute a waiver of any and all claims. The Inspector/Inspection Company shall have five business days to respond to the claim. If the Inspector/Inspection Company fails to satisfy the claim, <u>liability shall be</u> limited to a refund of the price paid for the Inspection and Report.

#### **Definition of Conditions**

AS = Appears Serviceable: The item appeared to be in working or usable condition with no major discrepancies noted.

**R** = Repair: The item was at or near the end of its useful lifespan. A certified professional should be contacted for further evaluation and repair.

**S** = Safety Issue: The item is considered a safety hazard and can cause harm to people or property. These items need to be repaired as soon as possible.


NI = Not Inspected: The item was not inspected during the inspection.

Sunshine Inspections Inc.


REPORT SUMMARY PAGE						
This is only a summa	This is only a summary of the inspection report and is not a complete list of discrepancies.					
Section	Condition#	Comment				
Grounds	4	Pump not working - Sprinklers not inspected				
Exterior	8	Wood decay to door casing - front entry				
Exterior	10	Settlement crack along the floor in the rear porch				
Exterior	13	Open wiring in one area - install junction cover box				
Roofing - Attic	14	Dated & deteriorated shingle tabs - Recommend licensed roofer assessment Trim back tree limbs				
Roofing - Attic	16	Clean out debris from gutters				
Roofing - Attic	17	Areas of wood decay to soffit & fascia panels				


Roofing - Attic	22	Attic access panel inaccessible - Due to undersized access panel
Electrical	26	Double tap breaker with copper & aluminum wiring connected - Recommend licensed electrician assessment
Plumbing	28	Hose bib in lawn not working
Plumbing	30	No water filter installed
Plumbing	31	Dated & rusted pressure tank
Plumbing	35	Open drain along front of home
Air Conditioning - Heat	38	Condenser - 2012 Air handler - Unknown date Air handler coils impacted with debris - Recommend servicing the AC system
Air Conditioning - Heat	42	Ductwork leaks found next to the air handler - needs sealing
Kitchen - Appliances	45	No GFCI outlet installed next to sink
Guest Bath	68	No GFCI outlet installed next to sink
Interiors	80	Closet door needs repair in guest bath
Interiors	83	Lights not working in laundry room
Interiors	84	Ceiling fan not working in the living room
Interiors	85	Replace batteries in smoke alarms
Small Shed	86	Roof leak found Trim back tree limbs
Large Shed	90	Missing glass panel to window
Large Shed	91	Wood decay to door casing & rusted entry door Interior door damaged
Large Shed	92	Spliced wiring & open junction box Missing spacer cover cap
Large Shed	93	Dated & deteriorated roof shingles
Large Shed	94	Wood decay to soffit & fascia
Horse Barn	96	Wood decay to wall panels & trim boards to one area

AS = Appears Serviceable NP = Not Present	<mark>R</mark> = Repair	<mark>S</mark> = Safety	NI = Not Inspected	
		1 Grounds		
Grading				
1) Grading Conditions	AS			
<u>Driveways - Sidewalks - Walk</u>	ways			
Driveway Material	Concrete			
2) Driveway Conditions	AS No	rmal cracks		
3) Sidewalk - Walkway Conditions	AS			
Irrigation				
4) Pump - Well	R Pu	mp not working -	Sprinklers not inspected	



AS = Appears Serviceable NP = Not Present	R = Repair	<mark>S</mark> = Safety	NI = Not Inspected
12) Porch Roof	AS		
Exterior Electric			
13) Outlets - Wiring	S Op	en wiring in one are	ea - install junction cover box





#### Attic Area


Attic Access	Closet
Method of Inspection	Attic area inaccessible
Roof Frame Type	Truss
18) Framing Conditions	ΝΙ
Attic Ventilation Type	Soffit/(Ridge) vents
Attic Insulation Type	Fiberglass - Unknown
19) Attic Insulation Conditions	NI
20) Sheathing	ΝΙ
21) Electric	ΝΙ
22) Attic Access Panel	<b>NI</b> Attic access panel inaccessible - Due to undersized access panel

NI = Not Inspected

#### AS = Appears Serviceable R = Repair S = Safety NP = Not Present



AS = Appears Serviceable R NP = Not Present	= Repair	<mark>S</mark> = Safety	NI = Not Inspected
	4	4 Electrical	
Service Drop - Weatherhead			
Electrical Service Type	The electric	al service is overhe	ad.
23) Electrical Service Conditions	AS		
24) Grounding Conditions	AS		
Main Disconnect Electrical Panel			
Electric Panel Location	The main e	lectric panel is locat	ed at the laundry area.
Panel Amperage Rating	200 Amp.		
25) Electrical Panel Conditions	S		
26) Breakers			n copper & aluminum wiring connected electrician assessment





#### Water Supply Lines

Supply Line Material

Copper


32) Supply Line Conditions

33) Plumbing Stops



AS

Drain - Waste Lines





#### Water Heater(s)

Water Heater Type

Electric & Solar - 2011

Water Heater Capacity

80 Gallon

36) Water Heater Conditions



37) Water Heater Temperature



Temperature - 115 degrees

## AS = Appears Serviceable NI = Not Inspected R = Repair S = Safety NP = Not Present 6 Air Conditioning - Heat **Air Condition - Heating** Split system - 2012 Type of Cooling System 38) AC Unit Conditions AS Condenser - 2012 Air handler - Unknown date Air handler coils impacted with debris - Recommend servicing the AC system 39) AC Line Conditions AS 40) Thermostat AS 41) Filter AS Ambient Temperature: 74 **Cool Air Temperature** Cool Air Temperature: 59 Heat Temperature: 85 degrees **Heat Temperature** 42) AC Ductwork R Ductwork leaks found next to the air handler - needs sealing

# AS = Appears ServiceableR = RepairS = SafetyNI = Not InspectedNP = Not Present



43) Registers (Vents)



44) AC Wall Unit


Appears Serviceable


AS = Appears Serviceable NP = Not Present	R = Repair	<mark>S</mark> = Safety	NI = Not Inspected	
	7 Kitc	hen - Applian	ces	
Electrical Conditions				
45) Electrical Conditions	S No (	GFCI outlet installed no	ext to sink	
46) Lighting Conditions	AS			
<u> Kitchen Sink - Counter tops - (</u>	<u>Cabinets</u>			
47) Counter Conditions	AS			
48) Cabinet Conditions	AS			
49) Sink Plumbing Conditions	AS			
50) Sink Faucet Condition	AS			
<u>Appliances</u>				
51) Stove or (Cook-top) - Range Condition	AS			
52) Hood Fan Conditions	NP No	hood fan installed	d	
53) Dishwasher Conditions	AS			
54) Refrigerator Condition	AS			
55) Ice-maker	AS			
56) Microwave	AS			
57) Washing Machine	AS			


AS = Appears Serviceable NP = Not Present	R = Repair	<mark>S</mark> = Safety	NI = Not Inspected	
58) Washing Machine - Water - Drain Lines	AS			
59) Dryer Conditions	AS			
60) Dryer Vent	AS			

AS = Appears Serviceable NP = Not Present	<mark>R</mark> = Repair	<mark>S</mark> = Safety	NI = Not Inspected	
	8	Master Bath		
Electrical Conditions				
61) Electrical Conditions	AS			
62) Vent Fan Conditions	AS			
Bathroom Sink				
63) Counter - Cabinet Conditions	AS			
64) Sink Conditions	AS			
65) Sink Faucet Conditions	AS			
<u>Shower - Toilet</u>				
66) Shower Enclosure Conditions	AS			
67) Toilet Conditions	AS			

AS = Appears Serviceable NP = Not Present	R = Repair	<mark>S</mark> = Safety	NI = Not Inspected	
	9	Guest Bath		
Electrical Conditions				
68) Electrical Conditions	S No	GFCI outlet install	led next to sink	
69) Vent Fan Conditions	AS			
Bathroom Sink				
70) Counter - Cabinet Conditions	AS			
71) Sink Conditions	AS			
72) Sink Faucet Conditions	AS			
<u>Shower - Toilet</u>				
73) Shower Enclosure Conditions	AS			
74) Toilet Conditions	AS			









93) Roof

R

Dated & deteriorated roof shingles

94) Soffit and Fascia



Wood decay to soffit & fascia





95) AC Unit

AS

